



**Texas Department
of Insurance**



Welding Hazards Safety Program

Provided by

Division of
Workers'
Compensation

HS04-044A(12-06)

Welding Hazards Safety Program

Welding, cutting, and brazing are hazardous activities that pose a unique combination of both safety and health risks to more than 500,000 workers in a wide variety of industries. According to the Occupational Safety and Health Administration (OSHA), the risk from fatal injuries alone is more than four deaths per thousand workers over a working lifetime. Protecting the worker when performing welding operations depends on understanding of the hazards involved and the proper way to control them. Control of welding hazards includes avoiding eye injury, respiratory protection, ventilation of the work area, protective clothing, and having safe equipment to use.

Welding joins pieces of metal by the use of heat, pressure, or both. There are more than 80 different types of welding and associated processes. Some of the most common types of welding include: arc welding, which includes “stick” or shielded metal arc welding (SMAW), the gas-shielded methods of metal inert gas (MIG) and tungsten inert gas (TIG), plasma arc welding (PAW), and submerged arc welding (SAW). Other welding processes may use oxy-acetylene gas, electrical current, lasers, electron beams, friction, ultrasonic sound, chemical reactions, heat from fuel gas, and robots.

Brazing or soldering, involves a filler metal or alloy (a combination of metals), which has a lower melting point than the metal pieces to be joined. The filler materials (such as lead and cadmium) can be very toxic. Cutting involves heating the metal with a flame, and directing a stream of pure oxygen along the line to be cut.

Health Hazards of Welding

Gases and Fumes

Welding “smoke” is a mixture of very fine particles (fumes) and gases. Many of the substances in welding smoke, such as chromium, nickel, arsenic, asbestos, manganese, silica, beryllium, cadmium, nitrogen oxides, phosgene, acrolein, fluorine compounds, carbon monoxide, cobalt, copper, lead, ozone, selenium, and zinc can be extremely toxic.

Generally, welding fumes and gases come from:

- base material being welded or the filler material that is used;
- coatings and paints on the metal being welded, or coatings covering the electrode;
- shielding gases supplied from cylinders;

- chemical reactions which result by the action of ultraviolet light from the arc, and heat;
- process and consumables used; and
- contaminants in the air, for example vapors from cleaners and degreasers.

The health effects of welding exposures are difficult to list, because the fumes may contain so many different substances that are known to be harmful (depending on the factors listed above). The individual components of welding smoke can affect just about any part of the body, including the lungs, heart, kidneys, and central nervous system.

Welders who smoke may be at greater risk of health impairment than welders who do not smoke, although all welders are at risk.

Exposure to welding smoke may have short-term and long-term health effects.

Short-term (acute) health effects

- Exposure to metal fumes (such as zinc, magnesium, copper, and copper oxide) can cause metal fume fever. Symptoms of metal fume fever may occur 4 to 12 hours after exposure, and include chills, thirst, fever, muscle ache, chest soreness, coughing, wheezing, fatigue, nausea, and a metallic taste in the mouth.
- Welding smoke can also irritate the eyes, nose, chest, and respiratory tract, and cause coughing, wheezing, shortness of breath, bronchitis, pulmonary edema (fluid in the lungs), and pneumonitis (inflammation of the lungs). Gastrointestinal effects, such as nausea, loss of appetite, vomiting, cramps, and slow digestion, have also been associated with welding.
- Some components of welding fumes, for example cadmium, can be fatal in a short time. Secondary gases given off by the welding process can also be extremely dangerous. For example, ultraviolet radiation given off by welding reacts with oxygen and nitrogen in the air to form ozone and nitrogen oxides. These gases are deadly at high doses, and can also cause irritation of the nose and throat and serious lung disease.
- Ultraviolet rays given off by welding can also react with chlorinated hydrocarbon solvents, to form phosgene gas. Even a very small amount of phosgene may be deadly, although early symptoms of exposure—dizziness, chills, and cough—usually take 5 or 6 hours to appear. Arc welding should

never be performed within 200 feet of degreasing equipment or solvents.

Long-term (chronic) health effects

- Studies have shown that welders have an increased risk of lung cancer, and possibly cancer of the larynx (voice box) and urinary tract. These findings are not surprising in view of the large quantity of toxic substances in welding smoke, including cancer-causing agents such as cadmium, nickel, beryllium, chromium, and arsenic.
- Welders may also experience a variety of chronic respiratory (lung) problems, including bronchitis, asthma, pneumonia, emphysema, pneumoconiosis (refers to dust-related diseases), decreased lung capacity, silicosis (caused by silica exposure), and siderosis (a dust-related disease caused by iron oxide dust in the lungs).
- Other health problems that appear to be related to welding include: heart disease, skin diseases, hearing loss, chronic gastritis (inflammation of the stomach), gastroduodenitis (inflammation of the stomach and small intestine), and ulcers of the stomach and small intestine. Welders exposed to heavy metals such as chromium and nickel have also experienced kidney damage.
- Welding also poses reproductive risks to welders. A recent study found that welders, and especially welders who worked with stainless steel, had poorer sperm quality than men in other types of work. Several studies have shown an increase in either miscarriages or delayed conception among welders or their spouses. Possible causes include exposure to: (1) metals, such as aluminum, chromium, nickel, cadmium, iron, manganese, and copper; (2) gases, such as nitrous gases and ozone; (3) heat; and (4) ionizing radiation (used to check the welding seams).
- Welders who perform welding or cutting on surfaces covered with asbestos insulation are at risk of asbestosis, lung cancer, mesothelioma, and other asbestos-related diseases. Employees should be trained and provided with the proper protective equipment before welding near asbestos-containing material.

Other Health Hazards

Heat

- The intense heat of welding and sparks can cause burns. Contact with hot slag, metal chips, sparks, and

hot electrodes can cause eye injuries.

- Excessive exposure to heat can result in heat stress or heat stroke. Welders should be aware of the symptoms - such as fatigue, dizziness, loss of appetite, nausea, abdominal pain, and irritability. Ventilation, shielding, rest breaks, and drinking plenty of cool water will protect workers against heat-related hazards.

Visible Light, and Ultraviolet and Infrared Radiation

- The intense light associated with arc welding can cause damage to the retina of the eye, while infrared radiation may damage the cornea and result in the formation of cataracts.
- Invisible ultraviolet light (UV) from the arc can cause “arc eye” or “welder’s flash” after even a brief exposure (less than one minute). The symptoms of arc eye usually occur many hours after exposure to UV light, and include a feeling of sand or grit in the eye, blurred vision, intense pain, tearing, burning, and headache.
- The arc can reflect off surrounding materials and burn co-workers working nearby. About half of welder’s flash injuries occur in co-workers who are not welding. Welders and cutters who continually work around ultraviolet radiation without proper protection can suffer permanent eye damage.
- Exposure to ultraviolet light can also cause skin burns similar to sunburn, and increase the welder’s risk of skin cancer.

Noise

- Exposure to loud noise can permanently damage welders’ hearing. Noise also causes stress and increased blood pressure, and may contribute to heart disease. Working in a noisy environment for long periods of time can make workers tired, nervous, and irritable.
- If you work in a noisy area, the OSHA Noise Standard, Code of Federal Regulations (CFR) 1910.95, requires your employer to test for noise levels to determine your exposure. If your average noise exposure exceeds 85 decibels for over 8 hours, your employer must provide you with a choice of free hearing protection and annual hearing tests.

Musculoskeletal Injuries

Welders have a high prevalence of musculoskeletal complaints, including back injuries, shoulder pain, tendonitis, reduced muscle strength, carpal tunnel syndrome, white finger, and knee joint diseases. Work

postures (especially welding overhead, vibration, and heavy lifting) can all contribute to these disorders. These problems can be prevented by proper lifting techniques:

- not working in one position for long periods of time;
- keeping the work at a comfortable height;
- using a foot rest when standing for long periods;
- locating tools and materials conveniently; and
- minimizing vibration.

Safety Hazards of Welding

Electrical hazards

- Even though welding generally uses low voltage, there is still a danger of electric shock. The environmental conditions of the welder (such as wet or cramped spaces) may make the likelihood of a shock greater. Falls and other accidents can result from even a small shock; brain damage and death can result from a large shock.
- Dry gloves should always be worn to protect against electric shock. The welder should also wear rubber-soled shoes, and use an insulating layer, such as a dry board or a rubber mat, for protection on surfaces that can conduct electricity.
- The piece being welded and the frame of all electrically powered machines must be grounded. The insulation on electrode holders and electrical cables should be kept dry and in good condition. Electrodes should not be changed with bare hands, wet gloves, or while standing on wet floors or grounded surfaces.

Fires and explosions

- The intense heat and sparks produced by welding, or the welding flame, can cause fires or explosions if combustible or flammable materials are in the area.
- Welding or cutting should only be performed in areas that are free of combustible materials, including trash, wood, paper, textiles, plastics, chemicals, and flammable dusts, liquids, and gases (vapors can travel several hundred feet). Those that cannot be removed should be covered with a tight-fitting flame-resistant material. Doorways, windows, cracks, and other openings should be covered.
- Never attempt to weld containers that have held a flammable or combustible material unless the container is thoroughly cleaned or filled with an inert (non-reactive) gas. Explosions, fires, or release of

toxic vapors may result. Containers with unknown contents should be assumed to be flammable or combustible.

- A fire inspection should be performed before leaving the work area and within 30 minutes after the operation is completed. Fires extinguishers should be nearby.

Dangerous machinery

- All machines in the area with moving parts must be guarded to prevent workers' hair, fingers, clothing, etc. from getting caught.
- When repairing machinery by welding or brazing, power must be disconnected, locked out, and tagged so that the machinery cannot start up accidentally.

Trips and falls

- To prevent trips and falls, keep welding areas clear of equipment, machines, cables, and hoses, and use safety lines or rails.

Hazards of Welding in Confined Spaces

A confined space is a small or crowded area with limited access and little or no airflow or ventilation. Adequate ventilation is essential for working in confined spaces. Dangerous concentrations of toxic fumes and gases can build up very quickly in a small space. Unconsciousness or death from suffocation can occur rapidly because welding processes can use up or displace oxygen in the air. High concentrations of some fumes and gases can also be very explosive.

The following rules apply:

- All workers who may enter dangerous areas either on a regular basis or in an emergency situation should be trained on rescue procedures, self-contained breathing apparatus, use of safety equipment, and proper procedures for entering and exiting a confined space.
- The worker inside the confined space should be equipped with a safety harness, a lifeline, and appropriate personal protective clothing, including a self-contained breathing apparatus. (Never use an air-purifying respirator.)
- Gas cylinders and welding power sources should be located in a secure position outside of the confined space.
- A trained worker must be stationed outside of the confined space, and equipped with appropriate gear (including a fire extinguisher and personal protective equipment), to assist or rescue the worker

inside the confined space if necessary. If the worker notices any indications of intoxication or decreased alertness from the “inside” worker, the inside worker should be removed from the area immediately.

- All confined spaces should be tested before entering for toxic, flammable, or explosive gases or vapors, and oxygen level. Continuous air monitoring may be necessary during welding. No worker should enter a confined space where the percentage of oxygen is below 19.5% unless he or she is equipped with a supplied-air respirator.
- Never use oxygen for ventilation.
- Use continuous mechanical ventilation and a respirator whenever welding or performing thermal cutting in a confined space.
- All pipes, ducts, and power lines connected to the space, but not necessary to the operation should be disconnected or shut off. All shutoff valves and switches should be tagged and locked out so they cannot accidentally be restarted.
- All unnecessary torches and other gas or oxygen-supplied equipment should be removed from the confined space.

Hazards of Compressed Gases

Gas welding and flame cutting use a fuel gas and oxygen to produce heat for welding. For high-pressure gas welding, both the oxygen and the fuel gas (acetylene, hydrogen, propane, etc.) supplied to the torch are stored in cylinders at high pressure.

The use of compressed-gas cylinders poses some unique hazards to the welder. Acetylene is very explosive. It should be used only with adequate ventilation and a leak detection program. Oxygen alone will not burn or explode. At high oxygen concentrations, however, many materials (even those that are difficult to burn in air, such as normal dust, grease, or oil) will burn or explode easily. These are some rules to follow when using compressed gases.

- All cylinders should have caps or regulators.
- Only pressure regulators designed for the gas in use should be fitted to cylinders.
- Compressed gas cylinders, all pressure relief valves, and all lines should be checked before and during welding operations.
- Blowpipes must be kept in good condition and cleaned at regular intervals.
- Hoses and fittings should be kept in good condition

and checked regularly.

- Cylinders must be stored upright so that they will not fall over.
- Oxygen and fuel cylinders must be stored separately, away from heat and sunlight, and only in a dry, well-ventilated, fire-resistant area that is at least 20 feet away from flammable materials such as paint, oil, or solvents.
- Be aware of backfires and flashbacks that are usually caused by defective or incorrectly operated equipment. If a backfire occurs, shut off the blowpipe valves, oxygen first and then the fuel gas; shut off the oxygen and fuel gas cylinder valves; cool the blowpipe with water; and check the equipment for damage, particularly the nozzle. To prevent flashbacks use the correct lighting up procedure; ensure the blowpipe is fitted with spring-loaded non-return valves to prevent a backflow of gas into the hoses; use the correct gas pressure and nozzle size for the job; and maintain the equipment in good condition.
- Close cylinder valves when work is finished. Put valve protection caps in place and release pressure in regulators and hose lines before cylinders are moved or placed in storage.

Reducing the Hazards of Welding

Before beginning a welding job, it is important to identify the hazards for that particular welding operation. The hazards will depend on the type of welding, the materials (base metals, surface coatings, electrodes) to be welded, and the environmental conditions (outside or in a confined space, for instance).

Ask for Material Safety Data Sheets (MSDSs) to identify the hazardous materials used in welding and cutting products, and the fumes that may be generated. Make sure you know what you are welding before you start. Some fumes, such as those released from welding a cadmium-plated surface, can be fatal in a short time.

After identifying the hazard, appropriate control methods can be implemented.

Engineering Controls and Work Practices

Use less hazardous materials such as:

- Cadmium-free silver solders; and
- Asbestos-free electrodes, gloves, and hot pads.

Ventilation should be used to remove harmful fumes and gases. Local exhaust ventilation, which removes the fumes and gases at their source, is the

most effective method. This can be provided by a partial enclosure, such as a ventilated workbench, or by hoods positioned as close to the point of welding as possible. Ventilation systems should be cleaned and maintained regularly. General ventilation uses roof vents, open doors and windows, roof fans, or floor fans to move air through the entire work area. This is not as effective as local exhaust ventilation, and may simply spread chemicals around the workplace. General ventilation is often helpful, however, when used to supplement local ventilation.

For gas-shielded arc welding processes, local exhaust can be provided by means of an extracting gun, which can reduce worker exposure to welding emissions by 70%.

Hoods and ductwork should be constructed of fire-resistant materials.

Use shielding (barriers) to protect other people in the work area from the light of the welding arc, heat, and hot spatter.

Welding booths should be painted with a dull finish that does not reflect ultraviolet light (such as finishes that contain titanium dioxide or zinc oxide).

Acoustic shields between the worker and the noise source can be used to reduce noise levels. Alternatively, the machinery or process can be totally enclosed. Modify the process or follow safe work practices so that hazards are eliminated.

- Don't weld painted or coated parts. If possible, remove all surface coatings before welding.
- Use a water table under the plasma arc cutting to reduce fume and noise levels.
- Grind parts instead of air arcing.
- Use the sub arc process to minimize light and fumes created by a visible arc.
- Position yourself while welding or cutting so that your head is not in the fumes.
- Remove all nearby flammable or combustible materials before striking an arc or lighting a flame.
- Make sure that equipment is properly maintained, for example, replace worn insulation and hoses.
- Welding areas should be kept free of equipment and machines that could cause trips or falls.
- You can minimize the production of welding fumes by using the lowest acceptable amperage and holding the electrode perpendicular and as close to the work surface and possible.

- Arc welding should never be performed within 200 feet of degreasing equipment or solvents.

Personal Protective Equipment (PPE)

Personal Protective Equipment should always be used along with, but never instead of, engineering controls and safe work practices!

Eye protection should be used for all welding operations to protect the eyes from bright light, heat, ultraviolet light, and flying sparks. For the best protection, wear face shields or helmets and goggles. To keep slag and particles out of your eyes when removing your face shield, tip your head forward and keep your eyes closed.

Welding helmets, goggles, or other eye protectors must contain special filter plates or lenses for workers exposed to arc welding or cutting processes, and oxyfuel gas welding, brazing or cutting. The OSHA 29 CFR 1910, Subpart Q requires that workers performing welding and cutting operations are protected with filter lenses or plates.

Protective clothing which should be worn during welding (by welders and nearby workers) includes:

- fire-resistant gauntlet gloves;
- high-top hard-toed shoes;
- leather apron;
- faceshield;
- flame-retardant coveralls;
- safety glasses;
- helmets; and
- leggings or high boots.

Protective clothing should be made of wool, which does not ignite easily, or specially treated cotton fabrics. Sleeves and collars should be kept buttoned, and pants and shirts should be uncuffed. Capes and hard hats may also be required. Workers should use welding helmets (with appropriate filter lenses), not hand-held screens. When welding overhead, extra protection should be used, such as fire-resistant shoulder covers, aprons, head covers, leggings, and suits. Earplugs should be worn when sparks or hot spatter may get in the ears.

Since welders work with highly toxic materials, lockers should be provided so that work clothes are stored separately from street clothes.

Hearing protectors (ear plugs or ear muffs) should be used during noisy operations such as air arcing and grinding.

Respirators must be specific to the hazard, and fitted,

cleaned, stored, and maintained in accordance with OSHA's respirator standard. In addition, workers must receive training on how to use respirators properly. The National Institute for Occupational Safety and Health (NIOSH) recommends that respirators be worn whenever a carcinogen (cancer-causing agent) is present at any detectable concentration, or if any other conditions are present that might be immediately dangerous to life or health. A self-contained breathing apparatus should be worn when welding in confined spaces because welding may reduce the oxygen concentration in the air.

Air Monitoring

Routine air monitoring should be conducted to determine the levels of hazardous materials and noise in the welding area.

Medical Monitoring

Because welding emissions are so hazardous, NIOSH recommends that all workers who may be exposed to welding processes should receive medical exams at least once a year. The doctor should examine the lungs, skin and eyes, heart, and hearing, in addition to any other tests that are appropriate.

Training

All welders should receive training on the safe use of equipment and processes, safe work practices, and emergency procedures.

The Law

OSHA has standards that cover many aspects of welding work, including welding safety, welding in confined spaces, handling of compressed gases, fire and electrical safety, ventilation, protective equipment, and worker training. Insist on safe working conditions before welding. The following is a brief summary of some of the regulations that can apply to welders.

Workplace Exposure Limits

There is no OSHA standard for total welding smoke, but OSHA does set standards for individual components of welding smoke. Local exhaust or general ventilation must be provided to keep your exposure to toxic fumes, gases, or dusts below the OSHA permissible exposure limit.

However, NIOSH has concluded that welders can be harmed by welding smoke even when the concentrations of the individual components are well below OSHA permissible exposure limits. NIOSH recommends that welding emissions be reduced to the lowest feasible concentrations using state-of-the-art engineer-

ing controls and work practices.

Labels and Other Information

Under OSHA's 29 CFR 1910.252 (c)(1)(iv)(A), all containers of filler metal, electrodes, and flux materials should carry warning labels alerting the welder that welding produces hazardous fumes and gases. Base metals that contain or are coated with toxic materials (such as paints, lead, or mercury) should also be clearly labeled. Welding materials that contain carcinogens (cancer-causing agents) must carry a warning label stating that gases from the material may cause cancer. The employer must also keep MSDSs for all of these hazardous materials, and make this information readily available to all exposed workers. The MSDS must contain information on chemical ingredients, hazardous decomposition products from welding, safe handling procedures, protective measures, first aid procedures, and health effects of the welding material.

Signs

OSHA's standard for signs and tags (29 CFR 1910.145) requires that signs be used to warn workers of hazards that may lead to accidental injury. Signs should be posted in welding areas to warn workers of exposure hazards, and serve as a reminder for the need for protective equipment. Signs should also notify all workers in the area that eye injury may occur from looking at the welding arc.

OSHA's Welding Standard

Specific requirements for assuring the safety of welding, cutting, and brazing operations are covered under OSHA Standard 29 CFR 1910.252. Below are some selected requirements of the standard:

- Compressed gas cylinders must be kept away from radiators and other heat sources and stored upright in a well ventilated, dry location at least 20 feet from highly combustible materials such as oil. Cylinders should be kept away from elevators, stairs, or other spaces where they can be knocked over or damaged.
- Piping systems must be tested and proved gastight at 1 1/2 times the maximum operating pressure, and shall be thoroughly purged with air, before being placed in service. Service piping systems must be protected by pressure relief devices.
- Hoses showing leaks, burns, worn places, or other defects must be repaired or replaced.
- Cutters and welders must be suitably trained in the safe operation of their equipment and the safe use

of the process.

- The welder should be enclosed in an individual booth, or by non-combustible screens, that are painted with a finish of low reflectivity such as zinc oxide or lamp black (to absorb ultraviolet radiation). Other people next to the welding area must be protected by noncombustible or flameproof screens or be required to wear appropriate goggles. The booths or screens should permit circulation of air at the floor level.
- All movable fire hazards in the vicinity of welding operations must be taken to a safe place. If all the fire hazards cannot be moved, guards must be used to contain the heat, sparks, and slag.
- Suitable fire extinguishing equipment must be maintained ready for instant use.
- Firewatchers are required whenever welding or cutting is performed in a location where other than a minor fire might develop. A fire watch must be maintained for at least 1/2 hour after completion of welding or cutting operations to detect and extinguish possible smoldering fires.
- No welding, cutting, or other hot work shall be performed on used drums, barrels, tanks, or other containers until they have been thoroughly cleaned (a purge with an inert gas is also recommended).
- Eye protection must be used during all arc welding or arc cutting operations, gas welding, oxygen cutting, resistance welding, or brazing operations (the proper shade number should be selected).
- When a welder must enter a confined space through a manhole or other small opening, an attendant with a pre-planned rescue procedure must be stationed outside to observe the welder at all times and to put the rescue operation into effect, if necessary.
- Special ventilation and/or respirators are required in confined spaces, for cleaning compounds, when fluorine compounds, zinc, lead, beryllium, cadmium, and mercury are encountered, and when cutting stainless steel.
- Warning labels are required for all filler metals and fluxes containing fluorine compounds (fluorides).

New Welding Technologies

New technologies in welding, such as laser welding and electron beam welding, bring new hazards to the welder's environment. Special precautions must be taken when using these welding methods.

Laser Welding

Laser welding uses a focused beam of light to achieve very precise welds. The major hazard of this powerful beam is to the eyes, which can be partially blinded when hit with the beam. Special eye protection must be used, and care must be taken with any reflective surfaces since both the original and reflected beam are extremely dangerous.

Electron Beam Welding

This method uses a focused beam of electrons to produce high precision and deep penetration welds. Since x-rays are produced as a by-product, the process should be enclosed and shielded with lead or other materials suitable for preventing x-ray exposure. All doors, ports, and other openings must have proper seals and should be checked periodically to prevent x-ray leakage.

Operators should wear film badges to detect accidental radiation exposure. The high voltages required also present an electrical hazard.

Robot Welders

Many industries are beginning to use robot welders in place of human workers on the assembly line. This removes workers from the hazard, but focuses on job elimination rather than workplace improvements. In addition, industrial-welding robots can injure workers. For additional safety and health information on welding hazards please refer to the Occupational Health and Safety Administration; the American Federation of State, County and Municipal Employees; or the Texas Department of Insurance (TDI), Division of Workers' Compensation (DWC).

Remember to practice safety. Don't learn it by accident.

The Texas Department of Insurance, Division of Workers' Compensation has the following safety and health publications with information on welding hazards:

- Confined Space (Safety Training Program)
- Welding, Cutting, and Brazing Checklist
- Compressed Gas Cylinders (Take 5)
- Confined Space (Sample OSHA Written Program)